

Rafael Flores
Senior Vice President
& Chief Nuclear Officer
rafael.flores@luminant.com

P O Sox 1002 6322 North FM 53 Gien Roso, TX 76043

T 254 697 5690 G 817 569 0403 P 254 697 6652

CP-201300001 TXX-13002 Ref. # 10CFR50.73

January 16, 2013

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555-0001

SUBJECT:

COMANCHE PEAK NUCLEAR POWER PLANT (CPNPP)

DOCKET NO. 50-446

UNIT 2 AUTOMATIC REACTOR TRIP DUE TO LOW STEAM GENERATOR WATER LEVEL LICENSEE EVENT REPORT 446/12-002-00

Dear Sir or Madam:

Pursuant to 10CFR50.73(a)(2)(iv)(A), Luminant Generation Company LLC (Luminant Power) hereby submits enclosed Licensee Event Report (LER) 446/12-002-00, "Unit 2 Automatic Reactor Trip Due to Low Steam Generator Water Level" for Comanche Peak Nuclear Power Plant (CPNPP) Unit 2.

This communication contains no licensing basis commitments regarding CPNPP Units 1 and 2.

Should you have any questions, please contact Jack Hicks at (254) 897-6725.

Sincerely,

Luminant Generation Company LLC

Rafael Flores

Fred W Madden

Director, Oversight & Regulatory Affairs

A member of the STARS Alliance

Callaway · Comanche Peak · Diablo Canyon · Palo Verde · San Onofre · South Texas Project · Wolf Creek

TEAD

U. S. Nuclear Regulatory Commission TXX-13002 Page 2 of 2 01/16/2013

Enclosure

c - E. E. Collins, Region IV
B. K. Singal, NRR
Resident Inspectors, Comanche Peak

NRC FORM 36	6 U.S	. NUCLE	AR REC	SULATORY C	ОММ	ISSION	API	PROVED	B)	Y OMB NO. 315	50-0104		EXPIRES	5 10/31/2013
(10-2010) LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block)						Estimated burden per response to comply with this mandatory information collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA/Privacy Section (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects.resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.								
1. FACILITY N	AME						2. [DOCKET	NL	UMBER	to respond	3. PA	AGE	tion.
COMANCHE PEAK NUCLEAR POWER PLANT					1	050004				1 of 4				
4. TITLE	<u> </u>	1100	LLFux	IOVVEI		111	<u> —</u>	00000		10			1 01	*T
I INIT 2 ALI	UNIT 2 AUTOMATIC REACTOR TRIP DUE TO LOW STEAM GENERATOR WATER LEVEL													
	ENT DATE	10		LER NUMBER		_							IES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO	монтн	DAY	YEAR	F7	ACILITY NAME			ET NUMBER	
11	17	2012	2012	- 002 -	00	01	16	2013	1	ACILITY NAME		DOCK	ET NUMBER	
9. OPERATING	3 MODE						D PUF			THE REQUIREME	NTS OF	10 CFR	8: (Check all tha	at apply)
1			□ 20.2201(b) □ 20.2203(a) □ 20.2201(d) □ 20.2203(a) □ 20.2203(a)(1) □ 20.2203(a) □ 20.2203(a)(2)(i) □ 50.36(c)(1)			a)(3)(i) a)(3)(ii a)(4) (1)(i)(A	i) ii) A)	☐ 50.73(a)(2)(i)(C) ☐ 50.73(a)(2)(ii)(A) ☐ 50.73(a)(2)(ii)(B) ☐ 50.73(a)(2)(iii)			☐ 50.73(a)(2)(vii) ☐ 50.73(a)(2)(viii)(A) ☐ 50.73(a)(2)(viii)(B) ☐ 50.73(a)(2)(ix)(A)			
10. POWER LE	EVEL		_	2203(à)(2)(ii)		50.36(c)(4)	Σ	50.73(a)(2)(iv		50.73(a)(2)(x)		
				2203(a)(2)(iii)		50.36(c)(2			L	50.73(a)(2)(v)		73.71(a)(4)		
1	100		20.2203(a)(2)(iv) 50.46(a)(3)				<u> </u>				☐ 73.71(a)(5) ☐ OTHER			
				2203(a)(2)(v) 2203(a)(2)(vi)] 50.73(a)(i] 50.73(a)(i			L	50.73(a)(2)(v) 50.73(a)(2)(v)		ு s்	pecify in Abstra	act below or in
			L 20.2			ENSEE CO	_		 CHI:		<u>/(U)</u>		INO I OITH GOG,	,
FACILITY NAME					· · · · · · · · · · · · · · · · · · ·					ELEPHONE NUMI	BER (Incl	ude Are	a Code)	
Timothy A.									L			_	7-6370	
		13. CON	IPLETE	ONE LINE FO	OR E	ACH COMF	ONE	ONENT FAILURE DESCRIBED IN THIS REPORT						
CAUSE	SYSTEM	сом	PONENT	MANU- FACTURER	REF	PORTABLE TO EPIX	L	CAUSE		SYSTEM	COMPO	NENT	MANU- FACTURER	REPORTABLE TO EPIX
			Ì											
•	14.	SUPPLE	MENTA	AL REPORT E	XPEC	CTED) <u> </u>		\neg	15. EXPEC	CTED	MOI	NTH DAY	YEAR
YES (If	es, compl	ete 15. F	EXPECT	ED SUBMISS	SION [DATE)	⊠ NC	ɔ		SUBMISS				
ABSTRACT (ritten line	es)	,			<u>.</u>	
power. A rods fully systems The caus regulator	At 1023 h y inserted respondence se of this r for the h	nours, the and all led norm to be event when the heater I	he Unit Il three mally du was the Drain p	t 2 reactor as Auxiliary Furing and for e planning poump discha	autor eedv ollow proce arge	matically water pur ving the e ess did n valve. T	tripp mps : event not pr The v	ed due started : covide in valve wa	to as nst	IPP) Unit 2 was low steam go sexpected as tructions for reassembled	jeneratos a resu mountir d withou	or wa ult of ng the ut pro	ter level. Althe reactor to air pressure perly suppo	Il control rip. All re rting the
pressure fatigue fa resulted level. Immedia to the ac	e regulato ailure whi in the los ate correctuator of	or which ich resu ss of on ctive act	n allowe ulted in ne main tions in eater Dr	ed vibration the loss of r Feedwate ncluded rep rain pump o	n to o f air a er pur blacer disch	occur in the and closump and a ment of the narge valve	he tu ure of an au the br	ibing. T if the He itomatic roken fit As a par	Thiseat eat re ittir	is eventually ter Drain pume eactor trip on ng and mount of the CPNPF	caused np disc low ste ting of P Corre	d a sw harge eam of the a ective	vage-lok fitti e valve. This generator wa ir pressure r Action Prog	ng s ater regulator gram,
alternate	e part if re	equired.			·					ins specific in ed otherwise.	structio	ons to	or installation	ı of an

2NRC FORM 366A LICENSEE EVENT REPORT (LER) U.S. NUCLEAR REGULATORY COMMISSION CONTINUATION SHEET								
1. FACILITY NAME	2. DOCKET	(6. LER NUMBER		3. PAGE			
COMANCHE PEAK	05000446	YEAR	SEQUENTIAL NUMBER	REV NO.	2 OF 4			
	33333440	2012	- 002 -	00	2 01 4			

NARRATIVE

I. DESCRIPTION OF THE REPORTABLE EVENT

A. REPORTABLE EVENT CLASSIFICATION

10CFR50.73(a)(2)(iv)(A), Any event or condition that resulted in manual or automatic actuation of any of the systems listed in paragraph (a)(2)(iv)(B) of this section including:

10CFR50.73(a)(2)(iv)(B)(1), Reactor protection system including: reactor scram or reactor trip 10CFR50.73(a)(2)(iv)(B)(6), PWR auxiliary or emergency feedwater system

B. PLANT CONDITION PRIOR TO EVENT

On November 17, 2012, CPNPP Unit 2 was in Mode 1 operating at 100% power.

C. STATUS OF STRUCTURES, SYSTEMS, OR COMPONENTS THAT WERE INOPERABLE AT THE START OF THE EVENT AND THAT CONTRIBUTED TO THE EVENT

There were no structures, systems, or components that were inoperable at the start of the event that contributed to the event.

D. NARRATIVE SUMMARY OF THE EVENT, INCLUDING DATES AND APPROXIMATE TIMES

On November 17, 2012, Comanche Peak Nuclear Power Plant (CPNPP) Unit 2 was in Mode 1 operating at 100% power. At 10:19, the fitting between the Unit 2 Heater Drain Pump Discharge Valve Pressure Regulator [EIIS: (SM)(P)(V)(RG)] and the adjacent in-line filter failed. The loss of air caused the Heater Drain Pump Discharge Valve to close as designed. This resulted in a total loss of Heater Drain Flow. The loss of flow resulted in a lowering feed pump suction pressure. The Condensate Low Pressure Feedwater Heater Bypass Valve and the Condensate Polishing Filter Bypass Pressure Control Valve opened on low feed pump suction pressure. At 1020 hours, Operators (Utility, Licensed) in the Unit 2 Control Room received several secondary alarms indicating a decrease in main Feedwater pump suction pressure. The control room operators properly responded to the plant indications per ABN-302, "Feedwater, Condensate, Heater Drain System Malfunction", and initiated a runback to 900 MWe. Prior to reaching 900 MWe at 10:21, Main Feed pump 2A tripped and auto initiated a runback to 700 MWe. Once Unit 2 was at 700 MWe. Steam Generator (SG) water levels were at approximately 43% and appeared to be stabilizing. The Reactor Operator (RO) noted a mismatch in steam flow and feed flow. The RO attempted to initiate an additional 100 MWe runback when the steam dumps closed as expected for the plant response. The closure of the steam dumps lowered steam flow and resulted in shrink in the Steam Generators causing all four Steam Generator water levels to decrease. When SG 2-03 reached 35.4%, an automatic reactor trip occurred at 10:23. All control rods fully inserted, and both Motor Driven Auxiliary Feedwater Pumps and the Turbine Driven Auxiliary Feedwater Pump started as expected as a result of the reactor trip.

E. THE METHOD OF DISCOVERY OF EACH COMPONENT OR SYSTEM FAILURE, OR PROCEDURAL PERSONNEL ERROR

Operators (Utility, Licensed) in the Unit 2 Control Room received alarms indicating a loss of main feedwater pump suction pressure.

2NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT (LER) (10-2010) **CONTINUATION SHEET** 1. FACILITY NAME 2. DOCKET 6. LER NUMBER 3. PAGE SEQUENTIAL NUMBER REV YEAR COMANCHE PEAK 05000446 3 OF 4 2012 002 00

NARRATIVE

II. COMPONENT OR SYSTEM FAILURES

A. CAUSE OF EACH COMPONENT OR SYSTEM FAILURE

Not applicable – there were no component failures associated with this event. The valve functioned as expected with the loss of instrument air.

B. FAILURE MODE, MECHANISM, AND EFFECTS OF EACH FAILED COMPONENT

Not applicable - there were no component failures associated with this event.

C. SYSTEMS OR SECONDARY FUNCTIONS THAT WERE AFFECTED BY FAILURE OF COMPONENTS WITH MULTIPLE FUNCTIONS

Not applicable - there were no component or system failures associated with this event.

D. FAILED COMPONENT INFORMATION

Not applicable - there were no component failures associated with this event.

III. ANALYSIS OF THE EVENT

A. SAFETY SYSTEM RESPONSES THAT OCCURRED

Both Motor Driven Auxiliary Feedwater Pumps and the Turbine Driven Auxiliary Feedwater Pump started as expected as a result of the reactor trip.

B. DURATION OF SAFETY SYSTEM TRAIN INOPERABILITY

Not applicable - No safety system trains were inoperable during this event.

C. SAFETY CONSEQUENCES AND IMPLICATIONS OF THE EVENT

This event is bounded by the CPNPP Final Safety Analysis Report (FSAR) accident analysis which assumes conservative initial conditions which bound the plant operating range and other assumptions which reduce the capability of safety systems to mitigate the consequences of the transient.

A loss of normal Feedwater resulting from pump failure, valve malfunction, or loss of offsite power leads to a reduction in the capability of the secondary system to remove heat generated in the reactor core. These events are analyzed in Section 15.2.7 of the CPNPP FSAR which uses conservative assumptions in the analysis to minimize energy removal capability of the Auxiliary Feedwater system.

The event of November 17, 2012, occurred at 100 percent reactor power, and all safety systems functioned as designed. The event is bounded by the FSAR accident analysis that assumes an initial power level of 102 percent and the worst single failure in the Auxiliary Feedwater system for a loss of Feedwater event. There were no safety system functional failures associated with this event. The FSAR analysis shows that a loss of normal Feedwater does not adversely affect the core, the reactor coolant system, or the steam system. Therefore, this event posed no threat to the health and safety of the public.

Based on the above, it is concluded that the health and safety of the public were unaffected by this condition and this event has been evaluated to not meet the definition of a safety system functional failure per 10CFR50.73(a)(2)(v).

2NRC FORM 366A LICENSEE EVENT REPORT (LER) U.S. NUCLEAR REGULATORY COMMISSION CONTINUATION SHEET								
1. FACILITY NAME	2. DOCKET		6. LER NUMBER	3. PAGE				
COMANCHE PEAK	05000446	YEAR	SEQUENTIAL NUMBER	REV NO.	4 OF 4			
	030000	2012	- 002 -	00	4014			

NARRATIVE

IV. CAUSE OF THE EVENT

The cause of this event was that the planning process did not provide instructions for mounting the air pressure regulator for the Heater Drain pump discharge valve. The valve was reassembled without properly supporting the pressure regulator which allowed vibration to occur in the tubing. This eventually caused a swage-lok fitting fatigue failure which resulted in the loss of air and closure of the Heater Drain pump discharge valve. This resulted in the loss of one main Feedwater pump and an automatic reactor trip on steam generator low level.

V. CORRECTIVE ACTIONS

Immediate corrective actions included replacement of the broken fitting and mounting of the air pressure regulator to the actuator of the Heater Drain pump discharge valve.

A comprehensive walkdown of Unit 1 and Unit 2 secondary system air operated valves was conducted by a multi-disciplined team to identify other potential issues with the mounting of valve operator sub-components. One other condition was found with the regulator installed without direct mounting. If the valve was to fail due to loss of air the condition would not result in a reactor trip. This issue is being addressed in the CPNPP Corrective Action Program.

As a part of the CPNPP Corrective Action Program, procedures will be revised to ensure that the planning process contains specific instructions for the installation of an alternate part as appropriate.

VI. PREVIOUS SIMILAR EVENTS

There have been no previous similar reportable events at CPNPP in the last three years.